info@mar-blau.com
Club Náutico Arenal - C/ Roses 1, 07600 Arenal - Palma de Mallorca - Spain
(+34) 619 789 884

Bénéteau Oceanis 473

159.000 €



Description

Bénéteau Oceanis 473 is a modern cruiser with very spacious interiors, large cockpit (2 wheels) and excellent sailing performance. Full battened mainsail, Furling genoa, Bow thrusters, new Teak deck (2022), 2 electric fridges, Radar, autopilot, 3/4 cabins version with 3 heads, are some of the features that may attract your attention.

The Bénéteau Oceanis 473 is in excellent condition, moored in Mallorca, and available for viewing.

https://youtu.be/E-d0Nb77l_g

General Information

Year:	2002	Engine:	Yanmar
Length:	14,30	Power:	100 HP
Flag:	Belgian	Reference:	MB20490
Material:	GRP	Location:	Mallorca

Dimensions

LOA:	14,30	Waterline Length:	13,36
Beam:	4,31	Draft:	2,10
Ballast:	3.209 Kg	Hull Length:	14,15

Distribution

Cabins:	4	Salon	
Kitchen		Bathrooms:	3
Berths:	9	Salon Berths	
Chart Table			

Engine - Plumbing - Electricity

Engine Model:	4JH3-HTE
Fuel Type:	Diesel
Power per Engine:	100
Engine Hours:	1460
Number of Showers:	4
Battery Capacity:	577 Ah

Engine Type:	Inboard
Number of Engines:	1
Number of Cylinders:	4
Water Capacity:	600
Number of Batteries:	4

Equipment Engine

- Shaft transmission
- Holding tank
- Deck shower
- Electric bilge pump
- Shore power
- Voltmeter
- Twin wheels
- Electric pressurized water system
- Manual bilge pump
- Boiler
- Battery charger

Electronics

- Compass
- Speed/Log
- GPS plotter
- Radar
- Echo sounder
- Wind
- VHF radio with DSC
- Autopilot

Rigging - Sails

- Boom vang
- Furling Genoa
- Lazy bag
- Spreader Lines: 2
- Main
- Lazy Jack
- Number of Masts: 1

Various Equipment

- Teak deck
- Gangway
- Electric windlass
- Music, sound systems
- Spray hood
- Bathing platform
- Oven
- Electric Fridge
- Teak in cockpit
- Bow thrusters
- Anchor with chain
- Bimini
- Marine WC
- Gas stove
- Twin sink

Photos






























All data reflected in this sheet is offered with the best intentions, however, we will not be responsible for possible errors reflected in the text and we recommend an on-board inspection for verification. This document is not contractual.