

X-50

225.000 €

Description

The X-50 is a racing-cruiser built in Denmark, offering top-class sailing performance, exceptional build quality and incredible comfort. The X-50 offers two very distinct sailing experiences: regattas and family cruising. Three cabins, three heads, air conditioning, a spacious and uncluttered cockpit, two steering wheels, a generator and a water-making system are just some of the features that are sure to catch your eye. The X-50 is moored in Mallorca and available for viewing.



General Information

Year:	2005	Engine:	Volvo Penta
Length:	15,24	Power:	75
Flag:	Spanish	Reference:	MB20492
Material:	GRP	Location:	Mallorca

Dimensions

LOA:	15,24	Waterline Length:	13,14
Beam:	4,28	Draft:	3,00
Ballast:	4.960	Hull Length:	15,24

Distribution

Cabins:	3	Salon	
Kitchen		Bathrooms:	3
Berths:	8	Salon Berths	
Chart Table			

Engine - Plumbing - Electricity

Engine Model:	D2-75	Engine Type:	Inboard
Fuel Type:	Diesel	Number of Engines:	1
Power per Engine:	75	Number of Cylinders:	4
Diesel Capacity:	345	Water Capacity:	500

Number of Showers: 3

Equipment Engine

- Sail drive
- Twin wheels
- Electric pressurized water system
- Manual bilge pump
- Boiler
- Battery charger
- Voltmeter

- Folding propeller
- Holding tank
- Deck shower
- Electric bilge pump
- Shore power
- Diesel generator
- Ammeter

Electronics

- Compass
- Wind
- VHF radio with DSC
- Autopilot

- Speed/Log
- GPS plotter
- Radar
- Navtex

Rigging - Sails

- Backstay tensioner
- Main
- Self-tailing winches
- Lazy bag
- Spreader Lines: 3


- Boom vang
- Furling Genoa
- Lazy Jack
- Number of Masts: 1
- Rig Type: Fractional

Various Equipment

- Air conditioning
- Teak in cockpit
- Bow thrusters
- Electric windlass
- TV
- Bimini
- Marine WC
- Oven
- Electric Fridge
- Watermaker

- Teak deck
- Gangway
- Life raft
- Anchor with chain
- Music, sound systems
- Spray hood
- Gas stove
- Twin sink
- Freezer

Photos



All data reflected in this sheet is offered with the best intentions, however, we will not be responsible for possible errors reflected in the text and we recommend an on-board inspection for verification. This document is not contractual.