

Nordia 45

25.000 €

Description

The Nordia 45 is a blue water cruiser with a steel hull and ketch rig. Its lines are unmistakable, typical of these Dutch sailing yachts: a semi-enclosed central cockpit, a transom with Bounty-style portholes, and a wooden bowsprit with decorative features.



The vessel has suffered a leak which has caused partial flooding inside the hull, submerging the engine.

The engine is seized, and the boat requires a general overhaul, particularly of the electrical system, the electronics and all its equipment. The woodwork and floors do not appear to have been affected.

Furthermore, the teak deck has several areas of rust that require attention.

The advertised asking price is nominal, and will allow the buyer to invest in its refurbishment to once again enjoy this beautiful Nordia 45.

Prior to the leak, the boat was fitted with the following equipment: a hydraulic bow thruster, a hydraulic submersible swim platform, mainsail, mizzen, genoa and jib in good condition, a genoa furler, a in-mast furling mainsail and mizzen, and rigid boom supports.

General Information

Year:	1977	Engine:	Perkins
Length:	13,65	Power:	76
Flag:	British	Reference:	MB20488
Material:	Steel	Location:	Mallorca

Dimensions

LOA:	14,90	Waterline Length:	10,10
------	-------	-------------------	-------

Beam:	3,84
-------	------

Draft:	1,90
--------	------

Distribution

Cabins:	3
Kitchen	
Berths:	8
Chart Table	

Salon	
Bathrooms:	2
Salon Berths	

Engine - Plumbing - Electricity

Engine Model:	4236
Fuel Type:	Diesel
Power per Engine:	76

Engine Type:	Inboard
Number of Engines:	1
Number of Cylinders:	4

Equipment Engine

- Shaft transmission

- Wheel

Rigging - Sails

- Boom vang
- Furling Genoa
- Staysail
- Self-tailing winches
- Bowsprit
- Spreader Lines: 1
- More Information: 2020

- Furling Main
- Mizzen
- Winches
- Spinnaker pool
- Number of Masts: 2
- Rig Type: Ketch

Various Equipment

- Teak in cockpit
- Electric windlass
- Marine WC
- Oven
- Electric Fridge

- Bow thrusters
- Anchor with chain
- Gas stove
- Sink

Photos



and we recommend an on-board inspection for verification. This document is not contractual.